

6/7/23

Driscoll School Project
Change Order #27 Summary

<u>Change Proposal Number</u>	<u>Change Value</u>
ATP 193R3, ASI 42, Paint Colors	\$13,819.00
ATP 202R1, ASI 76, Deleted Corridor Lights LC6	(\$30,000.00)
ATP 229, ASI 68, Play Area Fence Clarifications	\$5,090.00
ATP 239, RFI 500, Bay Windows Inside Corner Flashing	\$34,594.00
ATP 244R1, ASI 71, Area A Exterior Elevations	\$1,763.00
ATP 245R1, RFI 523, Central Display Flair Walls	\$0.00
ATP 249R1, RFI 642, Bean Soffit in Room 47100	\$0.00
ATP 254R1, RFI 525, Roof Duct Modifications	\$6,105.00
ATP 259, ASI 79, Mass Notification Sequence Clarifications	\$2,722.00
ATP 260, RFI 577, Jamb Detail at S05	\$2,517.00
ATP 261, RFI 577, Added Blocking for Climbing Wall	\$2,408.00
ATP 264, RFI 634, Basement Door frame Hight Conflicts	\$1,835.00
ATP 265, RFI 510, Sewer Tie-In from B to SMH-2	\$1,104.00
ATP 266R1, RFI 638, Gym Defibrillator Cabinet	\$0.00
ATP 267, RFI 347, MP Technology Room - Sliding Doors	\$0.00
ATP 268, Black Break Metal Sill at Trespa	\$0.00
ATP 269, RFI 622, Multipurpose Room Fin Tube Plenum	\$0.00
ATP 270, RFI 666, C2 Fixtures Behind the Stage Wall	\$7,982.00
ATP 282, RFI 647, Tamper Switch Tie to Fire Alarm	\$2,172.00
ATP 284, FRI 526, Fuel Fill Core Openings Rework	\$0.00
ATP 285, RFI 65, Floor Drain at Outdoor Storage 1437	\$5,830.00
ATP 287, S37 and S39 Bump-Out	\$0.00
ATP 290, Miscellaneous Masonry Rework	\$0.00
ATP 292, Rework Projector Screen Brackets	\$0.00
Total Change Order Value	\$57,941.00

ATP 193R3, ASI 42, Paint Colors **\$13,819.00**
 Owner Scope Change to add paint accent colors identified for the Project Areas on Floors 3 and 4

ATP 202R1, ASI 76, Deleted Corridor Lights LC6 **(\$30,000.00)**
 Per Arch/MEP coordination, uplighting of corridor ceilings was not required.

ATP 229, ASI 68, Play Area Fence Clarifications **\$5,090.00**
 Modifications to the base of the fence gate to work with the ramp at the PreK/K play area. The stanchions adjacent to the gate conflicted with the typical support bracket and were modified to coordinate with the finish grade.



6/7/23

ATP 239, RFI 500, Bay Windows Inside Corner Flashing \$34,594.00

It was determined in the field that the installation of a flashing piece at the intersection of the bay window phenolic panel return and the brick relieving angle would provide an additional measure of protection for the bay window soffit.

ATP 244R1, ASI 71, Area A Exterior Elevations \$1,763.00

Several DCU units were relocated to the east wall over the areaway in order to reduce the distance of the piping runs previously shown to go to the roof level to improve performance. Reframing was required to support the units from the wall.

ATP 245R1, RFI 523, Central Display Flair Walls \$0.00

No cost clarification of the central display case as documented on A625 in the bid documents.

ATP 249R1, RFI 642, Bean Soffit in Room 47100 \$0.00

Construction contingency to build GWB beam enclosures as shown in the Exterior Wall Sections series and Exterior Details series (ref: 2/A316, 10/A522).

ATP 254R1, RFI 525, Roof Duct Modifications \$6,105.00

The roof duct was reconfigured to allow appropriate clearance for the electrical panel door.

ATP 259, ASI 79, Mass Notification Sequence Clarifications \$2,722.00

Owner Scope Change to allow custom messages for the Mass Notification System

ATP 260, RFI 577, Jamb Detail at S05 \$2,517.00

Modifications to the detail of the opening at the wall outside the copy room required additional clearance for the installation of the window framing and jamb stud support.

ATP 261, RFI 577, Added Blocking for Climbing Wall \$2,408.00

Owner Scope Change for climbing wall installations required additional blocking

ATP 264, RFI 634, Basement Door frame Height Conflicts \$1,835.00

Coordination of 2 basement custodian storage doors with overhead steel beams necessitated reduced door heights.

ATP 265, RFI 510, Sewer Tie-In from B to SMH-2 \$1,104.00

The existing site sewer elevation was different than documentation provided to A/E, requiring an alternate connection detail. This was an unforeseen condition.

ATP 266R1, RFI 638, Gym Defibrillator Cabinet \$0.00

GMP Contingency for Defibrillator Cabinet for the Gymnasium as indicated on sheet A435



