Deferred Maintenance (Mini CIP)						
Location	Project Details		FY25	STAT	US	NOTES
	Remove Carpet, Replace with Tile - 5 rooms		\$30,000			
Baker	Paint 10 classrooms		\$10,000			
	Refurbish the Staircase by room 202 (the stairs used for recess)		\$50,000			
	Upgrade Electrical Service to Meet Code (inside and outside)		\$74,250		Waiting on Everso	urce
	Ceiling Work/Replaster Upper Level		\$20,000			
	New Drop Ceiling in Lower Level		\$10,000		To start afer scho	ol opening
	Paint Interior		\$90,000			
	Update Flooring (excluding bathrooms)		\$75,000			
Baldwin	HVAC: Heat Pumps		\$100,000		Waiting on Everso	urce to Commission
	Bathroom Renovation for ADA Compliance		\$135,000		To start afer scho	ol opening
	Window Shades		\$10,000			
	Build, Alter or Repair Walls		\$200,000			
	Contingency (10% of other)		\$71,425			
	Classroom Cabinet Millwork Repairs 2nd and 3rd Floor		\$50,000		2nd Floor Middl	le School Wing Completed Only
	2nd/3rd Floor Recondition (floors, paint)		\$600,000		2nd Floor Middl	le School Wing Completed Only
	Library Recondition (floors, paint, and millwork)		\$75,000			
	Gym Renovation (floors, painting, and scoreboard)		\$70,000		Scoreboard com	pleted Only
	Electrical Repairs/Replacements Needed for 1994 Bldg		\$100,000			
Lincoln	Replace All Ceiling Tiles in Building		\$150,000			
	Bathroom Renovation (\$30k per bathroom)		\$90,000			
	Cafeteria Reconditioning (floors, paint, and millwork)					
	Kitchen Renovation					
	Finish Removing Wallpaper in Basement, Paint (about 40% done)					
	Upgrade Main Electric to Building to Install Heat Pumps		\$250,000		Anticipated comple	etion week of 8/26
Hayes	Replace Wall Mats with New School Name (paid from maintenance budget FY 24)		\$0			
	Replace School Name on Front of School (paid from maintenance budget FY 24)		\$0			
	Replace Carpets in 10 Classrooms		\$60,000			
Lawrence	Repair / Replace Stair Treads, Various Stairways		\$40,000			
	Multi Purpose Room (MPR) Curtain/Drapes (cords are broken and don't work)		\$10,000			
	Update Sound Board and Control Panel in MPR (Including speakers)		\$15,000		Waiting on Install [Date
Runkle	Lighting Not Working in MPR		\$35,000		Waiting on Install [Date
	Paint (all classrooms and hallways)					
	Flooring Refresh - where and is this a replacement					
			\$2,420,675			
		Cumulative	\$2,420,675			